ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	5	Jakkuru
Street ID	**Street Name**	**Significant Landmark**
W0835, W0488, W0492, W0831, W0496, W1177	NA, Panathur Colony Rd, 60 Feet Main Rd	bellahalli
Segment No.	**Total Length (m)**	
5/C-W0835/S082449	208.79	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	70.74	77.642585	13.099599	77.643227	13.099569	W0831	W1177
2	59.75	77.642858	13.099885	77.643409	13.099862	W0835	W0831
3	21.90	77.643134	13.099888	77.643134	13.100086	W0492	W0488
4	56.40	77.642972	13.100102	77.643492	13.100100	W0488	W0831

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to Roads and Drains at bellahalli in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	6000000	2016
Year	**Type of Work**	**Other Work Type**
2016 - 2017	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to Roads and Drains at bellahalli in ward no 05 Byatarayanapura Sub-Division Yelahanka zone	005-17-000003
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/130/2016-17	24/10/2016	60 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/10/2016	23/10/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL		0.00
Phone No.	**E-Mail ID**	
9449863065		

Field Inspection Details

Number of Trees	Any Other Information	Name
3		CHANDRAPPA
Date of Inspection	**Remarks**	
05/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0835, W0488, W0492, W0831,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0835, W0488, W0492, W0831,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	05/12/2016	04/01/2017	COMPLETED
SE	VASU K M	05/12/2016	04/01/2017	COMPLETED
EE	YARAPPA REDDY	05/12/2016	04/01/2017	COMPLETED
AEE	J N LOKESH	05/12/2016	04/01/2017	COMPLETED
AE	CHANDRAPPA	05/12/2016	04/01/2017	COMPLETED
AE	CHANDRAPPA	05/12/2016	04/01/2017	COMPLETED

Zone: YELAHANKA **Ward No:** 5 **Ward Name:** Jakkuru **Street ID:** W0835, W0488, W0492, W0831,